


1/24



2 / 24

FIG. 2 A




FIG. 2 B






FIG. 3




4 / 24

FIG. 4




5 / 24

FIG. 5




6 / 24

FIG. 6



7 / 24


FIG. 7



S03P1121


8 / 24

FIG. 8




9 / 24

FIG. 9




10/24



11 / 24

FIG. 11




10/528723

S03P1121

12/24

FIG. 12



13/24

FIG. 13 A





FIG. 13 B



- MARK INDICATING THAT TRANSFER IS COMPLETED
- ▨ MARK INDICATING THAT TRANSFER IS BEING PERFORMED
- MARK INDICATING THAT TRANSFER IS UNNECESSARY
- ▨ NEWLY ARRIVED THUMBNAIL

14/24

FIG. 14 A



 TRANSFER RESERVATION MARK

FIG. 14 B



15/24




FIG. 15 A





FIG. 15 B

16/24

FIG. 16



17/24

FIG. 17 A





FIG. 17 B




10/528723

S03P1121


18/24

FIG. 18




19 / 24

FIG. 19



20 / 24

FIG. 20







FIG. 21


22 / 24

FIG. 22



23 / 24

FIG. 23



10/528723
S03P1121

24/24

FIG. 24

